






## Oversleeve Removal

### Installation Instructions



**⚠ WARNING: Overheating heat-shrinkable tubes will produce fumes that may cause irritation. Use adequate ventilation and avoid charring or burning. Consult MSDS for further information.**

**Raychem Corporation**  
**Commercial & Industrial Infrastructure Division**  
300 Constitution Drive  
Menlo Park, CA 94025-1164  
Tel (800) 545-6258  
Fax (800) 611-2323  
Fax-on-Demand (800) 329-4494  
www.raychem.com